The Changing Nature of Building Contents

Jan Lagerblad

IKEA Group Risk Management



Jan Lagerblad



Småland, Sweden

Fire & Rescue Services:

Fire Protection Engineer

IKEA:

- Risk Manager (Sweden)
- Area Risk Manager (AP)
- Safety & Security specialist (Concept owner)
- Fire Safety Manager



Agenda:

- IKEA Group introduction
- IKEA Fire Risk Handling
- The Changing Nature of Building Contents
 - Fire load goods & range configuration
 - Type of storage solutions
 - New fire risks
 - Building components



The Changing Nature of Building Contents IKEA Store Perspective





1952









11 new stores in nine countries



139,000



IKEA.com > 1 billion visits

TOP 5 SELLING COUNTRIES






The IKEA Catalogue was printed in 212 million copies




IIKEA Group stores 690 million visits



The IKEA range 9,500 products





Total number of IKEA Store: 348 Stores

Shopping Centre Distribution Centre (DC)



IKEA – Fire Risk Handling

Historical perspective:

Katastrofbrand ödelade Ikea



435 anställda

J örlagskvällens svåra hrand är den första som drabbat Bea vid Kungens kurva. Måbellunet and klart
enutnarn 1965, bet var da nover. Europas störta travlans. Byggkostanferna njägjek till eicka 17 miljoner
ka. Det rundt anlikellunet milere 60 meter i djameter.
Det intilliggande lagge och denda ytan i kompleket år
stilliggande lagge och tottale ytan i kompleket år
35,000 kvaraminetes. Möslellunet speedsitter i dig 435
sessenskarfarinnetes. Möslellunet speedsitter i dig 435

Skador för 50 miljoner

M söbelhuset Ikea vid Kungens kurva i Stockholm eldhärjades på lördagskvällen M så svårt att man måste bygga ett nytt hus. Det uppgav platschefen Hans Ax vid midnatt, då branden fortfarande rasade i det stora möbelkomplexet. Skadoria uppgår till cirka 50 miljoner kr. Branden började vid 20.30-tiden i neonskylten på taket. Tre brandkårer tillkallades men man hade ingen möjlighet att stoppa den våldsamma branden. Via luftintagen fortsatte den ner i huset. Även den intilliggande lager- och kontorsbyggnåden härjades mycket svårt.

Se sidan liunodita

Fire: The Kungens Kurva store, Sweden - 1970.



Fire: The Wallau store, Germany - 1984.



IKEA – Fire Risk Handling

Historical perspective:



- Israel 2011
- NOT IKEA Group owned unit!



IKEA – Fire Risk Handling

Concept development – Building content



Development IKEA concept:

- Concept layouts
- Sales solutions
- Logistic handling
- Store equipment
 - Restaurant
- Money handling
 - IKEA range
- Packaging concept
 - Etc.



Risks:

- Fire
- Accident
 - Crime
- Natural hazards
 - Etc.




IKEA Safety & Security "proven solutions"

More then 50 years of experience! IKEA GROUP - 305 stores!




Inter IKEA Systems Manual







National codes

IKEA Group Risk Manual



IKEA Store









IKEA Engineering & Construction Manual

International standards: Design:

IKEA Group Risk Manual











FM

NFPA





The Changing Nature of Building Contents IKEA Store Perspective:

- Fire load goods & range configuration
- Type of storage solutions
- Building components
- New fire risks



- 1958 1970
 - Most wooden products
 - More or less everything in cardboard boxes









The Changing Nature of Building Contents Fire load – Goods & Range configuration

- 1980 2013
- More plastic products in our range
 - New products / range
 - Not packaged in cardboard boxes
 - Shrink wrapping










The Changing Nature of Building Contents


Fire load – goods & range configuration



Test at FM1999-2000

- Exposed Expanded Plastics
- Rolled mattresses
- IKEA testing 1980-
 - SP, FM, Vds, Viking, CCI, UL
- Challenge:
 - Few international standards?
 - In-rack solutions flexibility?
 - IKEA standards Approval authorities
 - Sensible solutions Flue space
 - Expensive installations





- Showroom
- Restaurant
- Market hall
- Self serve furniture area
- Warehouse





- Showroom
- Restaurant
- Market hall
- Self serve furniture area
- Warehouse





- Showroom
- Restaurant
- Market hall
- Self serve furniture area
- Warehouse





- Showroom
- Restaurant
- Market hall
- Self serve furniture area
- Warehouse





- Showroom
- Restaurant
- Market hall
- Self serve furniture area
- Warehouse

High fire load – Focus area!



BOLINGBROOK PRODUCT CLASSIFICATION

RANGE GROUPING	ARTICLE NO.	ARTICLE MANE	PIECES STORED IN WAREHOUSE RACKING	PIECES PER PALLET	PALLETS STORED IN WAREHOUSE RACKING	COMMODITY CLASSIFICATION
Fabric sofa programs	20088729	EKTORP LS SB CVR IDEMO DBLU	- 6	32	0.19	W.
Fabric anfa programa	20103158	MEA STHEM EASY CHR ROSTANGA WHT NA	6	4	1.50	EXP PLASTIC
Fabric sofa programs	20118145	KARLSTAD OHSE FRM LNG OLTH NA	2	-3-3	2.90	EXP PLASTIC
Fabric sofa programs	20118447	KARLSTAD CHR CVR KORNDAL BLU	2	49	5.04	IV.
Fabor sufa programa	20118659	KARLSTAD OVE LVST KORNDAL GRN		24	0.25	IV:
Fabric sofa programs	20110683	KARLSTAD CVR LVST KORNDAL RED	3	24	0.13	67.
Extric sofa programs	20118701	KARLSTAD CVR SOFA KORNDAL BLU	- 3	- 24	0.13	TV.
Fabric sofa programs	20122802	EKTORP NN CRN SO FRM 2+2LNG GLTH NA	- 5	1	5.00	EXP PLASTIC
Fabric sofa programs	20123946	LILLBERG N OSH SET NA	33	-11	3.00	TH.
Fabric sofa programs	20129502	TYLÓSAND LYST CVRIARM REPHET PURPUS	2	.24	0.08	- 11
Pabric sufa programa	30047360	EKTORP LS S8 CVR BLEIGNGE WHT	- 6	.30	0.17	an-
Fabric sofa programs	30073194	AUJPPAN LYST FRM LNG CLTH NA	9	3	3.00	EXP PLASTIC
Fabot sofa programs	30107368	TYLOSAND 35 CVR EVEROD ORG US	3	20	0.15	TV:
Fabric sofa programa	30107373	TYLÖSAND OVR SOFA EVERÖD ORG US	- 5	24	0.21	. IV
Fabric sofa programa	30107677	EKTORP LET-HND CHSE DVR BERGVIK BGE	2	.56	0.04	- III
Fabric sofa programs	3010/1924	KRAMFORS CVR LYST ULLEVI GRN US	3	44	0.07	
Fabric sofa programs	30118140	KARLSTAD FTST FRM LNG CLTH NA	8	74.	8.00	EXP PLASTIC
Fabric oofs programs	20118437	KARLSTAD CHR CVR KORNOAL RED	4	48	0.08	EXP PLASTIC
Fabre sofa programa	30119601	EKTORP SLCVR CORNER 2+2 IDEMO BUX	4	20	0.20	EXP PLASTIC
Fabric sofa programs	30152940	TYLÓSÁND LÝST CYR/1 ARM EVER BLK US	- 4	40	0.10	EXP PLASTIC
Pabos sufa programa	40086733	EKTORP SLOVR CORNER 2+2 IDEMO DBLU	2	30	0.13	EXP PLASTIC
Fabric sofa programs	40106383	ENTORP LS SB CVR TOFTAHOLM BLU:	3	- 56 1	0.05	101
Fabric sofa programs	48106702	TYLOSAND CVR 1-8T BEC REPHILT DBRUS	- 2	48	0.04	30
Fabric sofa programs	40107377	TYLÖBAND RT CHSE CVR REPHULT WHT US.	1	24	0.04	EXP PLASTIC
Fabric sofa programs	40118413	KARLSTAD FTBT CYR LINNERYD NAT	18.	120	6.13	EXP PLASTIC
Fabric sofa programs	40118677	KARLSTAD CVR LVST LINNERVD NAT	- 3	- 56	0.05	EXP PLASTIC
Fabric sofa programs	40118781	KARLSTAD CVR/ADON CHSE KORNDAL GRN	2	48	6.64	EXP PLASTIC
Fabric sofa programs	40122801	EKTORP NN CHR FRM LNG OLTH NA	40	- 4	10.00	EXP PLASTIC
Fabric sofa programs	40123606	KARLSTAD CVR CHAISE LNG KORNDAL BRN	4	48	0.09	EXP PLASTIC
Fabot sofa programs	40152500	TYLOSAND CVR FTST EVEROD SUK US	- 3	43	0.06	EXP PLASTIC
Fabric sofa programs	50047590	EKTORP SLCV CRN 2+2 BLEKINGE WHT.		10	0.22	EXP PLASTIC
Fabric sofa programs	60073107	TYLÓSANO LVST FRIMI ARM LNG CLTH NA	12	2	6.00	EXP PLANTIC

Approx.10000 articles 2000 in Warehouse (Rack storage)




Classification according:

- Chapter 23 of the 2006 International Fire Code (IFC).
- NFPA 13-2007, Standard for the Installation of Sprinkler Sprinklers.



The Changing Nature of Building Contents Fire load – Warehouse goods configuration



- Generally the volume of plastic have increased
- More Exposed Expanded Plastic

BOLINGBROOK - 11 DECEMBER 2008 - STORAGE IN WAREHOUSE (CLASSIFICATION; NO. OF PALLETS; PERCENTAGE OF PALLETS)



The Changing Nature of Building Contents Fire load - Comparison study (2010)



Polyurethane





IKEA Mattresses





Latex



Standard Commodity: The Exposed Expanded **Group A Plastic**



The Changing Nature of Building Contents Fire load – Sprinkler test (2012-13)





- Develop NFPA sprinkler protection criteria -Expanded exposed Group A plastic commodity
- Vertical barriers
- NFPA 13 (2016) revision process



The Changing Nature of Building Contents

Fire load - Showroom & Market hall configuration



- Fire load
 - Range development
 - Different load
- Sales solutions
 - Obstructions
 - Storage height



We have a lot to be proud of!







Cost-saving

Branding

Efficiency

Simplicity

Ease of shopping

Sustainability









The Changing Nature of Building Contents Type of storage solution: Sales solutions



- Storage Sales
 - Change of fire load
 - Goods -storage
 - Range selling



The Changing Nature of Building Contents Fire load – Sprinkler design

Figure 1: Store Layout Ground floor




Table 7-1 Area Classification European Standard and NFPA 13

Area	European standa	ards	NFPA 13		
	Hazard classification	Goods classification	Hazard classification	Goods classification	
Self serve and warehouse	HHS	4	Storage	Group A expanded exposed plastics	
Activity area	HHS	3	Storage	4	
Goods unloading	HHS	4	Storage	Group A expanded exposed plastics	
Market hall	HHS	3	OH2	4	
Entrance	OH3	-	OH1	-	
Restaurant	OH3	-	OH1	-	
Show room	OH3	3	OH2	4	
Office	OH1	-	LH	-	
Tech. rooms	OH1	-	OH1	-	

IKEA Engineering & Construction manual



The Changing Nature of Building Contents New fire risks



li-ion 14.4 V





- Lithium batteries
- Storage
- Usage
- Battery management



The Changing Nature of Building Contents Fire load – Building components



- Combustible insulation
- Roof & Walls
- Freezers
- Solar panels



The Changing Nature of Building Contents Fire load – Building components





IKEA Standard

Hot Work!





Most things still remain to be done. A glorious future!



